### **Audubon Elementary School**

#### **Fair Condition**



Audubon Elementary School was built in 1967 and is now 54 years old. It contains approximately 38,629 square feet.

The assessment is based on observations only, no detailed engineering inspections were performed. Recent renovations include updated administration area w/renovated principal's office, front desk & breakroom with secure entry-way, (2) new small group rooms, and (2) kitchen serving lines. Additional work includes painting hallways, and new ceilings/lights in cafetorium. Exterior work includes expanded carpool lanes, additional parking and dumpster enclosure.

**DEFERRED MAINTENANCE:** 

\$1,150,000

- Exterior Façade
- · Exterior Door repaint/replacement
- · Window System
- Roofing
- Drainage
- Electrical
- · Wire Management
- · Plumbing fixtures
- Signage
- Additional electrical outlets

### **Broadmoor Elementary School**

#### **Good Condition**



Broadmoor Elementary School was re-built in 2017 and is now 4 years old. It contains approximately 86,180 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.


**DEFERRED MAINTENANCE:** 

\$0

No deferred maintenance cost was observed at this time.

#### **Broadmoor Middle School**

#### **Poor Condition**



Broadmoor Middle School was built in 1962 and is now 59 years old. It contains approximately 86,455 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

This school is scheduled to be renovated in the new tax plan. Currently this school is closed.

**DEFERRED MAINTENANCE:** 

\$6,181,532

- Driveways/Sidewalks
- Exterior Façade
- · Window Systems
- Roofing
- · Interior Finishes
- · Mechanical Piping
- · Wire Management
- Electrical
- · Special Systems
- Drainage
- Stairway

### **Broadmoor High School**

### **Fair Condition**



Broadmoor High School was built in 1958 and is now 63 years old. It contains approximately 146,079 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

This school is scheduled a \$25,000,000 major renovation in the new tax plan.

**DEFERRED MAINTENANCE:** 

\$9,495,135

- Drainage
- · Window Systems
- Exterior Façade
- · Exterior Doors
- Roofing
- Interior Renovations
- Additional HVAC
- 2 Pipe HAC Conversion
- Wire Management
- Signage
- Electrical
- Parking

### **Riveroaks Elementary School**

#### **Fair Condition**



Riveroaks Elementary School was built in 1968 and is now 53 years old. It contains approximately 37,900 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,567,600

- · Driveway/Parking
- · Exterior Doors
- Exterior Façade
- Signage
- Building A Flooring, Millwork
- · Special Systems
- Freezer/Cooler
- Kitchen
- Building B Restrooms
- Roofing
- Drainage/Erosion

### **Sherwood Middle School**

#### **Fair Condition**



Sherwood Middle School was built in 1966 and is now 55 years old. It contains approximately 91,661 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$2,623,158

- · Exterior Façade
- Sidewalks
- Fencing
- · Window Systems- Building A
- · Exterior Doors
- Soffit
- Roofing
- Signage
- Ceilings
- Plumbing
- Electrical
- · Special Systems
- · Wire Management
- · Restroom Renovations
- 2 Pipe HVAC Conversion

### **Southeast Middle School**

#### **Fair Condition**



Southeast Middle School was built in 1973 and is now 48 years old. It contains approximately 105,349 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$3,247,749

- Signage
- Lighting
- Exterior Façade
- · Carpool/Bus Drive
- Site Drainage/Erosion
- Ceilings in Building A
- · Markerboards in Building A
- Wire Management
- Roofing

### **Twin Oaks Elementary School**

### **Fair Condition**



Twin Oaks Elementary School was built in 1972 and is now 49 years old. It contains approximately 42,411 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

This school had minor flooding in 2016, repairs to flooring, millwork and new paint were done.

**DEFERRED MAINTENANCE:** 

\$1,306,259

- Roofing
- · Carpool/Bus drive
- Exterior Façade
- Sidewalks
- Exterior doors (Building A)

### **Wedgewood Elementary School**

#### **Fair Condition**



Wedgewood Elementary School was built in 1977 and is now 44 years old. It contains approximately 52,283 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

A major renovation was done on this school in 2016. Work included new flooring, interior lights in classrooms, paint, playground equipment, & car-pool lane.

**DEFERRED MAINTENANCE:** 

\$1,820,600

- Parking/Sidewalk
- Exterior doors
- Exterior Facade
- Kitchen
- Electrical
- Plumbing
- Wire management

### **Brownsfields Elementary School**

#### **Poor Condition**



Brownfields Elementary School was built in 1956 and is now 65 years old. It contains approximately 35,372 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$4,280,012

- Driveway/Parking
- Playcourt
- Drainage/Erosion
- 2 Pipe HVAC Conversion
- ADA Accessibility
- · Freezer/Cooler
- · Interior Renovation
- · Kitchen Renovation
- · Wire Management
- · Special Systems

### **Claiborne Elementary School**

#### **Good Condition**



Claiborne Elementary was built in 2011 and is now 10 years old. It contains approximately 93,528 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$514,404

- Drainage
- Paving
- · Exterior façade
- Hardware
- Roofing
- · Interior Finishes- Dining Area and Kitchen
- Dining-Partition Wall
- · Special Systems

### **Forest Heights Elementary School**

### **Fair Condition**



Forest Heights Elementary was built in 1972 and is now 49 years old. It contains approximately 41,921 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$553,357

- · Soffits
- · Site Drainage
- · Exterior Façade
- Roofing
- · Ceiling-Building A
- · Flooring- Media Center
- Signage
- Kitchen
- Freezer
- Mechanical Piping
- · Special Systems

### **Glen Oaks Park Elementary School**

#### **Fair Condition**



Glen Oaks Park Elementary School was built in 1973 and is now 48 years old. It contains approximately 46,325 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

This school was flooded in 2016, only the items effected by the water such as floors, walls (up to 4', etc.) were renovated. Other items shown below in the deferred maintenance list still need to be addressed.

**DEFERRED MAINTENANCE:** 

\$1,426,810

- 2 Pipe HVAC System Needs Converting
- · ADA Accessibility
- Plumbing
- Parking
- Electrical
- Roofing
- Drainage/Erosion
- · Mechanical Piping System
- · Structural Cracks/ Facade
- Window Systems

### **Glen Oaks High School**

### **Good Condition**



Glen Oaks High School was built in 1960 and is now 61 years old. It contains approximately 179,179 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

This school was flooded in 2016, and as a result a major renovation was done to the existing buildings. Additionally, a new administration building w/media center (2019), and new practice gym (2021) were constructed. A renovated 8-lane asphalt track with field events are currently under construction

**DEFERRED MAINTENANCE:** 

\$462.800

- Exterior Facade
- Roofing
- Plumbing
- Electrical

## **Merrydale Elementary School**

### **Fair Condition**



Merrydale Elementary School was built in 1968 and is now 53 years old. It contains approximately 44,747 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$861,380

- · Additional HVAC
- · Kitchen renovations
- Parking / Driveways
- Electrical
- · Exterior doors
- Exterior Facade
- Minor plumbing
- · Minor Restroom renovations
- · Window System replacement Building C
- Fencing
- · Wire Management
- · ADA Accessibility
- Roofing

### **Northeast Elementary School**

#### **Fair Condition**



Northeast Elementary was built in 2002 and is now 19 years old. It contains approximately 99,584 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$541,112

- · Minor interior finishes
- Fascia
- Site drainage/erosion

### **Northeast High School**

### **Fair Condition**



Northeast High School was built in 2003 and is now 18 years old. It contains approximately 141,811 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$779,960

- Playcourts
- Drainage/Erosion
- · Exterior Façade
- Roofing
- Door Hardware
- · Band Room Carpet
- Special System
- Minor Parking
- Minor Kitchen Finishes

### **Sharon Hills Elementary School**

#### **Fair Condition**



Sharon Hills Elementary School was built in 1963 and is now 58 years old. It contains approximately 44,835 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.


**DEFERRED MAINTENANCE:** 

\$1,280,918

- Roofing
- Exterior Doors
- · Soffit/Fascia
- Sidewalks
- Playcourts
- Drainage
- Exterior Façade
- Minor Interior Finishes
- 2 Pipe HVAC System Needs Converting

## White Hills Elementary School

#### **Poor Condition**



White Hills Elementary School was built in 1960 and is now 61 years old. It contains approximately 34,719 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussion, with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

### **DEFERRED MAINTENANCE:**

\$2,482,408

- Paving
- Sidewalks
- Fencing
- Drainage
- Window System
- Exterior Doors
- Roofing
- Exterior Façade
- Interior Finishes Building E Admin, Dining
- · Kitchen Renovations
- Mechanical
- Wire Management
- Add HVAC
- · Special Systems
- 2 Pipe HVAC Conversion

### **Belfair Elementary School**

#### **Fair Condition**



Belfair Elementary School was built in 1950 and is now 71 years old. It contains approximately 30,449 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,339,756

- 2 Pipe HVAC System Needs Converting
- · Driveway/Carpool Lane
- Exterior Façade
- Drainage/Erosion
- Roofing
- Sidewalk
- Playcourt
- · ADA Accessibility
- Mechanical Piping

## **Capitol Elementary School**

### **Good Condition**



Capitol Elementary School was built in 2008 and is now 13 years old. It contains approximately 75,575 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$378,030

- · Exterior façade
- · Minor parking
- · Erosion repairs
- · Site drainage
- Roofing
- · Minor interior repairs
- · Wire management
- · Electronic media center maintenance

## **Crestworth Elementary School @ old Crestworth MS**

**Fair Condition** 



Crestworth Elementary was built in 1972 and is now 49 years old. It contains approximately 35,936 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

Ongoing renovations are in progress. New paint throughout, update admin area, new LED lights in all areas, new boiler, etc.

**DEFERRED MAINTENANCE:** 

\$1,364,280

- Paving
- Playcourts
- Fencing
- · Exterior Façade
- Roofing
- Drainage
- Exterior Doors
- Signage
- Minor Plumbing
- Minor Electrical
- Wire Management
- Insulation

### **Crestworth Pre-K Center**

#### **Fair Condition**



Crestworth Elementary was built in 1972 and is now 49 years old. It contains approximately 35,936 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

The elementary school is moving to the newly renovated Crestworth MS. This site will become a new pre-K center. All of the deferred maintenance cost shown below still apply to this site.

**DEFERRED MAINTENANCE:** 

\$2,569,424

- Drainage/Erosion
- Exterior Façade
- Exterior Doors
- Soffits
- Fascia
- Ceilings
- Wire Management
- Plumbing Fixtures
- Clock
- Mechanical Piping
- Driveway/Parking

### **Delmont Elementary School**

### **Poor Condition**



Delmont Elementary School was built in 1955 and is now 66 years old. It contains approximately 39,102 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

#### **DEFERRED MAINTENANCE:**

\$1,789,128

- Drainage/Erosion
- · Exterior Façade
- Soffit
- Roofing
- · Minor Interior Finishes
- Additional HVAC
- Wire Management
- Driveway/Parking
- · Special Systems
- Gym/Stage Floor
- 2 Pipe HVAC Conversion

### **EBR Readiness Middle School @ old Beechwood**

**Poor Condition** 



Beechwood was built in 1963 and is now 58 years old. It contains approximately 31,113 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.


**DEFERRED MAINTENANCE:** 

\$3,080,000

- · Exterior Façade
- · Window Systems
- · Exterior Doors
- Roofing
- Drainage
- · Interior Finishes
- Kitchen Walls/Ceilings
- Additional HVAC
- Plumbing Fixtures
- Wire Management
- Electrical
- Special Systems
- Playcourt
- 2 Pipe HVAC Conversion

### **Istrouma High School**

### **Good Condition**



Istrouma High School was renovated in two phases first in 2017 and the second in 2018 and is now 4 years old. It contains approximately 194,561 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

The bulk of the deferred maintenance would be to renovate the last existing building on campus the Auditorium.

**DEFERRED MAINTENANCE:** 

\$2,200,500

- Auditorium
- Drainage/Erosion
- Roofing
- · Minor Interior Finish

### **Park Elementary School**

### **Good Condition**



Park Elementary School was built in 2019 and is now 2 years old. It contains approximately 78,508 square feet. This school was built on a new site, and at this time has no maintenance, mechanical or electrical issues.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$0

No deferred maintenance cost was observed at this time.

### **Progress Elementary School**

### **Good Condition**



Progress Elementary was built in 2013 and is now 8 years old. It contains approximately 86,456 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$432,280

- · Portable Wall at Multi-Purpose Area
- · Electrical Outlet Cover

### **Ryan Elementary School**

### **Fair Condition**



Ryan Elementary was built in 1969 and is now 52 years old. It contains approximately 45,776 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,309,900

- · Site Drainage
- Roofing
- Soffits
- · Kitchen Ceiling/Lighting
- · Special Systems
- · Wire Management
- · Mechanical Piping

## **Scotlandville Magnet High**

### **Fair Condition**



Scotlandville High School was built in 1958 and is now 63 years old. It contains approximately 182,020 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$2,202,664

- Driveways
- Drainage/Erosion
- Exterior Facade
- Roofing
- Minor Interior Finish
- Wire Management
- Electrical
- Kitchen Freezer/Cooler
- 2 pipe HVAC conversion needed

#### **Scotlandville Middle School**

#### **Fair Condition**



Scotlandville Pre-Engineering Magnet Academy was built in 1951 and is now 70 years old. It contains approximately 91,655 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$756,153

- Drainage/Erosion
- Driveway
- · Exterior Facade
- Soffits
- Roofing
- Signage
- · Flooring Dining
- · Mechanical Piping
- Electrical
- Special System

### **Winbourne Elementary School**

#### **Good Condition**



Winbourne Elementary School was built in 2007 and is now 14 years old. It contains approximately 74,340 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$408,870

- · Erosion/Drainage
- · Expansion Joint
- · Exterior Facade
- Minor Interior Finish
- Plumbing Fixtures
- · Special Systems

### **Arlington Prep Academy – Howell Park Elementary School**

**Fair Condition** 



Arlington Prep @ old Howell Park Elementary School was built in 1955 and is now 66 years old. It contains approximately 36,074 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies. This school had minor damage during the flood of 2016. Repairs were made and ADA upgrades were also performed.

This school is currently the site for the ESS students that were previously at the old abandoned Arlington Prep school.

**DEFERRED MAINTENANCE:** 

\$1,205,000

- 2 Pipe HVAC System Needs Converting
- Parking/Driveway
- Sidewalks
- Drainage/Erosion
- Roofing

### **Belaire High School**

### **Fair Condition**



Belaire High School was built in 1974 and is now 47 years old. It contains approximately 180,093 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies. Recent renovations include new competition track, new visitor bleachers, added field events, new seating in auditorium, and new marque sign.

**DEFERRED MAINTENANCE:** 

\$1,350,697

- · Driveways/Parking
- Sidewalks
- Fencing
- Exterior Doors
- Exterior Façade
- · Ceilings
- · Mechanical Piping
- · Wire Management
- Electrical
- · Plumbing fixtures
- Restroom Renovations

#### **EBR Readiness @ Old Brookstown**

#### **Fair Condition**



Brookstown Middle School was built in 1950 and is now 71 years old. It contains approximately 45,208 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$372,900

- · Exterior Façade
- Roofing
- · Erosion/Drainage
- · Wire Management
- Kitchen Wall

### **Greenbrier Elementary School**

#### **Fair Condition**



Greenbrier Elementary School was built in 1960 and is now 61 years old. It contains approximately 45,522 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

This school was affected by the 2016 flood. A major renovation was done to correct the damages. Work included new flooring, wall repairs, paint, and millwork. The items below were not corrected and still need to be addressed.

**DEFERRED MAINTENANCE:** 

\$1,274,616

- 2 Pipe HVAC System Needs Converting
- Exterior Façade
- Tree/Vegetation Removal
- Roofing
- Structural
- Drainage
- · Wire Management

### **LaBelle Aire Elementary School**

### **Fair Condition**



LaBelle Aire Elementary was built in 1972 and is now 49 years old. It contains approximately 61,918 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

A new 2000 sf multi-use building is currently under construction. The deferred maintenance items shown below still need to be addressed.

**DEFERRED MAINTENANCE:** 

\$340,549

- · Drainage/Erosion
- Roofing
- Exterior Façade
- Parking
- Fencing
- · Window Systems
- Kitchen Walls
- Flooring
- · Special Systems
- · Wire Management
- Driveway/Sidewalks
- Fencing

#### **Park Forest Elementary School**

### **Fair Condition**



Park Forest Elementary was built in 1973 and is now 48 years old. It contains approximately 50,900 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

This school was flooded in 2016, and repairs were done to fix the damage. Damaged flooring, paint and millwork were replaced. No upgrades were done at this time.

**DEFERRED MAINTENANCE:** 

\$2,036,000

- Fencing
- · Exterior Façade
- Roofing
- Interior Finishes
- · Wire Management
- Kitchen
- Plumbing
- · Mechanical Piping
- Sidewalks
- Erosion
- ADA Accessibility

#### **Park Forest Middle School**

#### **Fair Condition**



Park Forest Middle School was built in 1967 and is now 54 years old. It contains approximately 96,311 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

This school was flooded in 2016, and repairs were done to fix the damage. Damaged flooring, paint and millwork were replaced. No upgrades were done at this time.

**DEFERRED MAINTENANCE:** 

\$890,750

- ADA Accessibility
- Exterior Façade
- Roofing
- · Wire Management
- Restrooms
- Drainage/Erosion
- 2 Pipe HVAC Conversion

### **Northdale Superintendent Academy**

#### **Poor Condition**



Northdale Superintendant Academy was built in 1958 and is now 63 years old. It contains approximately 36,408 square feet. The mechanical piping systems, finishes, lighting, accessibility, window system and security are showing their age and have reached the end of their life cycle.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$2,603,172

- Driveway
- Drainage
- Windows
- Roofing
- Exterior Façade
- Exterior Doors
- Soffit/Fascia
- Interior Renovations
- Add HVAC

### **Villa de Rey Elementary School**

#### **Poor Condition**



Villa Del Rey Elementary School was built in 1958 and is now 63 years old. It contains approximately 48,623 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,397,588

- 2 Pipe HVAC System Needs Conversion
- Exterior Façade
- Drainage
- Roofing
- Mechanical Piping
- · Ceiling-Kitchen
- Driveway/Sidewalk
- · ADA Accessibility
- Plumbing
- Wire Management

## **Baton Rouge Center for Visual and Performance Arts**

**Fair Condition** 



Baton Rouge Center for Visual and Performing Arts was built in 1953 and is now 68 years old. It contains approximately 36,830 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$2,633,345

- · Exterior Doors
- Exterior Façade
- Interior Finishes (except for Building I)
- Kitchen Finishes
- Additional HVAC
- · Wire Management
- Plumbing
- · Special Systems
- · Window Systems

### **Baton Rouge Foreign Language Academic Immersion Magnet**

**Fair Condition** 



Baton Rouge FLAIM @ the old Valley Park site was built in 1968 and is now 53 years old. It contains approximately 86,264 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,509,620

- Driveway
- Exterior Façade
- Roofing
- Building B 2nd Floor Interior Finishes
- Drainage
- 2 Pipe HVAC Conversion
- · ADA Accessibility

**Baton Rouge Magnet High School** 

**Good Condition** 



Baton Rouge Magnet High School was built in 2012 and is now 9 years old. It contains approximately 270,011 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$0

No deferred maintenance observed at this time.

## **Bernhard Terrace Elementary School**

#### **Fair Condition**



Bernard Terrace Elementary School was built in 1927 and is now 94 years old. It contains approximately 37,195 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,636,580

- · Driveways/Parking
- Sidewalks
- Fencing
- Drainage
- · Exterior Façade
- Soffit
- Roofing
- · Wire Management
- 2 Pipe HVAC Conversion

### **Capitol Middle School**

### **Fair Condition**



Capitol Middle School was built in 2004 and is now 17 years old. It contains approximately 115,460 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,524,072

- · Parking/Driveway
- Site Repairs/Drainage
- Erosion
- Control Joint
- · Soffit and Fascia
- · Exterior Doors
- · Exterior Façade
- Windows
- · Expansion Joint
- · Plumbing Fixtures
- Stage Curtain
- Minor Interior Repairs
- · Wire Management

### **CTEC High School**

### **Fair Condition**



CTEC high school was built in 2018 and is now 3 years old. It contains approximately 35,821 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

This school is the technical high school used for training in HVAC, nursing, computers, etc.

**DEFERRED MAINTENANCE:** 

\$0

### **EBR Readiness Elementary School @ Old Greenville**

**Poor Condition** 



Greenville Elementary was built in 1956 and is now 65 years old. It contains approximately 44,465 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$4,401,850

- · Parking Curbs
- · Exterior Façade
- · Play courts
- Fencing
- Drainage
- · Window Systems
- Exterior Doors
- · Soffits/Fascia
- Canopies
- Roofing
- Wire Management
- Interior Finishes
- · Mechanical Piping
- Additional HVAC
- · Plumbing Fixtures
- Additional Electrical
- · Special Systems
- 2 Pipe HVAC Conversion

### **McKinley Middle School**

### **Good Condition**



McKinley Middle School was built in 2006 and is now 15 years old. It contains approximately 119,238 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$655,809

- · Exterior Façade
- Erosion
- · Expansion Joint
- Flooring
- Door Hardware

### **Melrose Elementary School**

#### **Fair Condition**



Melrose Elementry School was built in 1955 and is now 66 years old. It contains approximately 55,080 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$727,056

- Window
- · Erosion/Drainage
- · Exterior Façade
- Fascia
- Roofing
- · Restroom Renovations
- · Plumbing Fixtures
- · Parking curbs
- · Wire Management

## **Dufrocq Elementary School**

### **Good Condition**



The Dufrocq School was renovated in 2009 and is now 12 years old. It contains approximately 78,930 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$434,115

- Drainage
- Exterior Façade
- · Minor Interior finishes
- Roofing

### **Westdale Heights Academy**

#### **Poor Condition**



Westdale Heights Academic Magnet was built in 1959 and is now 62 years old. It contains approximately 40,912 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$4,050,288

- 2 Pipe HVAC System Conversion
- · Window System
- · Exterior Doors/Lighting
- Exterior Facade
- Interior Finishes
- Wire Management
- · Plumbing Fixtures
- Site Drainage/Erosion
- · Parking Repairs
- Roofing
- Canopies
- Signage
- Playcourts
- Special Systems
- Additional HVAC
- ADA Compliance

#### **Westdale Middle School**

#### **Fair Condition**



Westdale Middle School was built in 1956 and is now 65 years old. It contains approximately 106,475 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,975,492

- · Driveway/Parking
- Sidewalks
- Playcourts
- Fencing
- Drainage/Erosion
- Window System
- Soffit
- · Exterior Doors
- · Exterior Façade
- Roofing
- Interior Finishes
- · ADA Accessibility
- Additional HVAC
- · Mechanical Piping
- Electrical
- · Wire Management

### **Shenandoah Elementary School**

#### **Fair Condition**



Shenandoah Elementary was built in 1972 and is now 49 years old. It contains approximately 45,979 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$885,095

- · Exterior Façade
- Fascia
- · Metal Panels
- Drainage/Erosion
- Gutters
- Roofing
- · Ceilings Kitchen
- Interior Building A- Admin
- · Mechanical Piping
- Electrical
- · Wire Management
- · Special Systems
- Parking/Driveways

### **Woodlawn Elementary School**

#### **Good Condition**



Woodlawn Elementary School was built in 2009 and is now 12 years old. It contains approximately 83,625 square feet housing Pre-K thru 5th grade.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$459,937

- · Exterior Facade
- Plumbing
- Drainage
- Minor Roofing
- Minor Electrical
- Minor Interior Finishes

### **Woodlawn High School**

### **Good Condition**



Woodlawn High School was built in 2003 and is now 18 years old. It contains approximately 197,098 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,626,059

- Erosion
- Drainage
- Roofing
- · Exterior Doors
- · Wire Management
- · Ceiling Tiles
- Signage
- Flooring

#### **Woodlawn Middle School**

#### **Good Condition**



Woodlawn Middle School was built in 2006 and is now 15 years old. It contains approximately 119,524 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$657,382

- Drainage/Erosion
- Roofing
- Minor Interior Finishes

### **Buchanan Elementary School**

#### **Poor Condition**



Buchanan Elementary School was built in 1955 and is now 66 years old. It contains approximately 56,742 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

This school is scheduled to be relocated to the new McKinley ES, and the old site will be demolished for expansion of McKinley HS.

**DEFERRED MAINTENANCE:** 

N/A

- · ADA Accessibility
- · Window Systems
- Exterior Façade
- Gutters
- Playcourts
- Walls
- Flooring
- Additional HVAC
- Signage
- Kitchen Walls/Ceiling
- · Wire Management
- · Plaster Ceiling
- 2 Pipe HVAC Conversion

### **Glasgow Middle School**

#### **Poor Condition**



Glasgow Middle School was built in 1955 and is now 66 years old. It contains approximately 61,009 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$2,684,396

- · Driveways/Sidewalks
- Play courts
- Fencing
- Drainage/Erosion
- Exterior Façade
- Window System
- · Minor Roofing
- · Interior Finishes
- · Mechanical Piping
- Electrical
- Plumbing Fixtures

### **Highland Elementary School**

### **Poor Condition**



Highland Elementary was built in 1940 and is now 81 years old. It contains approximately 39,624 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$3,982,176

- · Parking/Sidewalks
- · Exterior Façade
- · Fascia/Soffits
- Signage
- Roofing
- Doors- Building A
- · Canopies
- · Interior Finishes
- Pipe Insulation
- Structural
- · Special Systems
- 2 Pipe HVAC Conversion

Liberty (Formerly "Lee") High School

**Good Condition** 



Liberty high school was built in 2016 and is now 5 years old. It contains approximately 191,740 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$0

No deferred maintenance was observed at this time.

### **McKinley High School**

### **Fair Condition**



McKinley High School was built in 1960 and is now 61 years old. It contains approximately 150,988 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

A major renovation is scheduled for McKinley HS in the new tax plan. At that time all deferred maintenance cost would be unnecessary.


**DEFERRED MAINTENANCE:** 

\$2,642,290

- · Sidewalk Repairs
- Drainage/Erosion
- Fencing
- · Exterior Façade
- · Soffit Buildings K, L
- Fascia Building K
- Roofing/Canopy
- Electrical
- · Wire Management
- · Minor Interior Finishes
- · Kitchen Renovations
- · Mechanical Piping
- Plumbing Fixtures
- · Special Systems
- Additional HVAC
- Athletic Track

### **Southdowns Elementary School**

#### **Poor Condition**



Southdowns Elementary School was built in 1949 and is now 66 years old. It contains approximately 33,442 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$2,173,730

- Drainage
- Exterior Façade
- · Window Systems
- · Ceilings-Dining/Administration Area
- · Stage Floor
- Additional HVAC
- · Wire Management
- · Special Systems
- · ADA Accessibility
- Exterior Doors
- · Mechanical Piping
- 2 Pipe HVAC Conversion

## **University Terrace Elementary School @ Polk**

**Good Condition** 



University Terrace @ Polk Elementary was built in 1959 and is now 62 years old. It contains approximately 37,526 square feet. A major renovation was done in this school in 2015, at that time most maintenance issues were addressed.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$206,393

- Site drainage
- Roofing
- Wire management

## **Magnolia Woods Elementary School**

#### **Fair Condition**



Magnolia Woods Elementary School was built in 1963 and is now 58 years old. It contains approximately 41,411 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,656,440

- Drainage/Erosion
- Windows
- · Exterior Doors
- Exterior Façade
- Roofing
- Interior Renovations
- Additional HVAC
- · Wire Management
- Sidewalks

### **Mayfair Lab School**

#### **Fair Condition**



Mayfair Lab School was built in 1961 and is now 60 years old. It contains approximately 36,225 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

A new Mayfair Lab is scheduled to be constructed in the new tax plan. At that time all deferred maintenance cost would be unnecessary.

**DEFERRED MAINTENANCE:** 

\$2,354,625

- Drainage/Erosion
- · Window System
- Exterior Façade
- · Exterior Doors
- Roofing
- Ceiling Multi-purpose Area
- Millwork Buildings C and D
- Additional HVAC
- 2 Pipe HVAC Conversion
- Structural
- · Wire Management

### **Wildwood Elementary School**

#### **Fair Condition**



Wildwood Elementary School was built in 1969 and is now 52 years old. It contains approximately 42,166 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,792,120

- Building A Exterior Door Replacement
- Building A Interior Finishes
- Kitchen Renovations
- · Minor Roofing
- Exterior Facade
- · Wire Management
- · Site Drainage/Erosion
- · ADA Repairs
- · Special Systems
- Electrical
- · Mechanical Pipes

## **Cedarcrest-Southmoor Elementary School**

#### **Fair Condition**



Cedarcrest Southmooor Elementary Schools was built in 1967 and is now 54 years old. It contains approximately 42,176 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,299,020

- Parking/Driveway
- Roofing
- · Minor Interior Finishes
- ADA Accessibility
- Exterior Façade
- Mechanical Piping
- · Wire Management
- Drainage/Erosion
- · Soffit/Fascia
- · Window Systems

### **Jefferson Terrace Academy**

#### **Good Condition**



Jefferson Terrace Pre-K-8 was built in 2020 and is now 1 years old. It contains approximately 125,050 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$0

### **LaSalle Elementary School**

### **Fair Condition**



LaSalle Elementary School was built in 1955 and is now 66 years old. It contains approximately 43,164 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,329,451

- · Exterior Façade
- Drainage
- Additional HVAC
- · Wire Management
- · Ceilings- Building A
- · Special Systems
- Tree Trimming

## **Parkview Elementary School**

### **Fair Condition**



Parkview Elementary was built in 1974 and is now 47 years old. It contains approximately 44,453 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$1,269,152

- · Exterior Façade
- · Exterior Doors
- Roofing
- · Site Drainage
- Fencing
- · Interior Finishes: Admin Area and Kitchen
- Electrical
- · Wire Management
- · Special Systems
- Mechanical Piping
- Wall Cracks

**Tara High School** 

**Fair Condition** 



Tara High School was built in 1970 and is now 45 years old. It contains approximately 166,599 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.


**DEFERRED MAINTENANCE:** 

\$3,207,030

- · Mechanical Piping
- Plumbing
- · Wire Management
- Driveway
- Drainage/Erosion
- Exterior Façade
- · Window Systems
- · Exterior Doors
- Roofing
- · Flooring Carpet
- Signage
- · Ceilings
- Interior Finishes Building D
- Kitchen
- · ADA Accessibility
- · Outdoor Athletic Facilities

### **Westminster Elementary School**

### **Fair Condition**



Westminster Elementary School was built in 1966 and is now 48 years old. It contains approximately 32,921 square feet.

The assessments and estimates that follow in this report are based solely on visual and not destructive observations, a review of existing reports, and discussions with the school facility personnel. Non-standard inspection methods may be required to further define the scope and cost to repair some of the noted deficiencies.

**DEFERRED MAINTENANCE:** 

\$3,259,179

- 2 Pipe HVAC System Needs Converting
- Additional HVAC Kitchen
- Interior Finishes
- · Fixture replacement
- · Exterior doors
- · Window system
- Site Drainage/ erosion
- Minor roofing
- Driveway/parking
- · Exterior façade
- · Water infiltration
- · Mechanical piping
- Wire management